

COMPLAINT INVESTIGATION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Tuesday, August 10, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Roanoke County	STA 12776+93 – 12796+50 MVP-RO-282	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- | | | | | |
|---|--|--|--|--|
| <input type="checkbox"/> Tree Felling | <input type="checkbox"/> Clearing/Grubbing | <input checked="" type="checkbox"/> Grading | <input type="checkbox"/> Trenching | <input type="checkbox"/> Stringing/Welding |
| <input type="checkbox"/> Lowering/Backfilling | <input type="checkbox"/> Final Restoration | <input type="checkbox"/> Temp. Stabilization | <input type="checkbox"/> Perm. Stabilization | <input type="checkbox"/> Dormant |

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Background: This investigation was conducted in response to a complaint (IR#: 300498) received on August 10, 2021 for the MVP ROW at 8741 Poor Mountain Road in the Bent Mountain area. The MVP ROW runs through this property from approx. STA 12762+41 to STA 12803+37.

Landowner Concerns:

1. Drilling encountered ground water in preparation for blasting the trench.
2. "Request immediate stop work to stop damage to aquifer."

Observations:

1. At the time of inspection, there was no evidence of sediment discharge from MVP ROW.
2. ECDs within the MVP LOD were installed per the approved plans and appeared to be functioning as designed.
3. ROW in this area is actively being graded and prepared for blasting the trench centerline.
4. Land disturbing activity ends at approx. STA 12796+50.

Comments: No corrective actions were noted during this inspection.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Tuesday, August 10, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, August 10, 2021

Figure 1: STA 12784+66 – Controls in place and functioning properly.

BRG: 152°SE (T) **LAT:** 37.173024 **LON:** -80.139050 ±16ft **ALT:** 2779ft



12784+66

Figure 2: STA 12786+00 – Controls in place and functioning properly. PPL drilling in preparation for blasting trench line.

BRG: 150°SE (T) **LAT:** 37.172626 **LON:** -80.138846 ±98ft **ALT:** 2777ft



12786

Figure 3: Wetland W-IJ93 – Controls in place and functioning properly.

BRG: 182°S (T) **LAT:** 37.172587 **LON:** -80.138736 ±16ft **ALT:** 2743ft



W-IJ93

Figure 4: STA 12788+00 – Controls in place and functioning properly.

BRG: 335°NW (T) **LAT:** 37.171978 **LON:** -80.138266 ±32ft **ALT:** 2880ft



12788-75

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, August 10, 2021

Figure 5: STA 12787+33 – Controls in place and functioning properly. PPL drilling in preparation for blasting trench line.



Figure 6: STA 12791+00 – Controls in place and functioning properly.



Figure 7: Stream S-IJ82 – Controls in place and functioning properly along stream S-IJ82 crossing.



Figure 8: Stream S-IJ82 – Controls in place and functioning properly along stream S-IJ82 crossing.

