

## FIELD INSPECTION REPORT

<b>Project Name:</b>	Mountain Valley Pipeline	<b>Inspector:</b>	Matthew Grant
<b>Inspection Date:</b>	Monday, August 22, 2022	<b>Project Contact:</b>	Brian Clauto
<b>Spread G: Giles</b>	AR GI 241.03, 241.02 St10820-10804	<b>Weather:</b>	Wet

**ACTIVE STAGE OF CONSTRUCTION:** (Check all that apply)

- Tree Felling     
  Clearing/Grubbing     
  Grading     
  Trenching     
  Stringing/Welding  
 Lowering/Backfilling     
  Final Grading     
  Temp. Stabilization     
  Perm. Stabilization     
 Dormant

- |  | Yes                                 | No                                  | N/A                      |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed?  | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |

- Comments: Inspected the following resources: S-YZ1, S-Z14
- MVP crews were on site and AR GI 241.03 repairs were being conducted.

**Routine Maintenance:** *(72-Hour Deadline from Notification)*

Access road 241.03 has areas of erosion and will require repair.

**Ineffective Controls:** *(24-Hour Deadline from Notification)*

St 10807+68 Retrieve sediment that is outside the limit of disturbance approximately 15 ft. to 20 ft. and restabilize the disturbed area.


ST 10806+00, STA 10808+00, & STA10815+00 sloughing of subsoil pile, repair and restabilize subsoil pile.

Designated stream S-YZ1 has been impacted approximately 2000 ft. with access road stone. Remove sediment/stone per FERC approval and land owner approval.

**Recommended Corrective Action:** Maintain and install all controls per the approved PSS&S.

**Deadline:** Various - See Comments

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

**Inspector Signature:** \_\_\_\_\_  \_\_\_\_\_

**Date:** Monday, August 22, 2022

# FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Monday, August 22, 2022

- Figure 1: Designated stream S-Z1 has been impacted by access road stone.



- Figure 2: AR GI 241.03 has areas of erosion that will require repair.



- Figure 3: St10805 subsoil stockpile has slipped and will require repair.



- Figure 4: St10806 subsoil stockpile has slipped and will require repair.



# FIELD INSPECTION PHOTO LOG

■ **Figure 5:** St10807+68 sediment has escaped off LOD.

