



Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant		
Inspection Date:	Wednesday, January 20, 2021	Project Contact:	Brian Clauto		
Spread G: Montgomery	ST11670-11766+76 ST 11980-11973 MLV 26	Weather:	Dry		

Montgomery		MLV 26									
☐ Tree Fel		STRUC	TION: (Check all that Clearing/Grubbing Final Grading	t apply)	Grading Temp. Stabilization		Trenching Perm. Stabilization			nging/Welding mant	
								Yes	No	N/A	
1.	Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?						\boxtimes				
2.		Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?							\boxtimes		
Areas of offsite sediment deposition observed?								\boxtimes			
 Comments: Inspected the following resources: S-MN21, S-MN22, S-EF65, S-EF62, S-IJ52 ECD's were in place and functioning at the designated crossings. Routine Maintenance: (72-Hour Deadline from Notification) St11749+50 P1 requires sediment removal. Ineffective Controls: (24-Hour Deadline from Notification) N/A Recommended Corrective Action: Maintain and install all controls per the approved PSS&S. 											
<u> </u>							<u> </u>				

Deadline: Within 72-Hour of Notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: _____

Date: Wednesday, January 20, 2021



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, January 20, 2021

Figure 1: Gate remains installed near St11670



 Figure 2: St11677+00 ECD's are installed and the area is temporarily stabilized.



Figure 3: St11749+50 P1 requires sediment removal.



<u>Figure 4</u>: St11973+00 ECD's are in place and the area remains stabilized.

