

Field Inspection

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Wednesday, January 22, 2020	Project Contact:	Brian Clauto
Spread: Giles Co. AR GI 234 AR GI 241.01 AR GI 256.02 ATWS1331,1333,1332 ,1360 MP 202.4, 205.9, 206.7-207.3, 214.2- 214.8	Spread G	Weather (Wet/Dry/Rain):	Dry
STAGE OF CONSTRUCT	ION: (Check all that apply)		
Clearing	Rough Grading	Trench Excavation	Pipe Assembly, Testing & Installation
Backfilling and Grade Restoration Final Grading & Stabilization			Other: Dormant

Yes No N/A
⊠ □ □

 \boxtimes

Comments:

- Inspected designated stream included: S-Q14, S-G32, S-E20, S-Y2, S-Y3, S-A32, S-NN11, S-NN12, S-NN13
- ECD's controls were in place and functioning at crossings.

Areas of offsite sediment deposition were observed?

applicable, manufacturer specifications?

At AR GI 256.02, erosion has occurred on and alongside road.

Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?

Are all control measures properly maintained in effective operating

condition in accordance with good engineering practices and, where

Alongside AR GI 256.02, check dams require maintenance.

Recommend Corrective Action: Maintain controls per the approved plan and annual standard and specs.

Deadline: Routine Maintenance 72 hours from notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: ____ Date: 2-10-2020



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline Date: Wednesday, January 22, 2020

Fig. 1 Check dams at AR GI 256.02 require maintenance.



Fig. 2 On AR GI-256.02 erosion has occurred on road.



 Fig. 3 At designated crossing S-NN12, ECD's are in place.



Fig. 4. At AR GI-234, additional matting has been installed.

