

## **COMPLAINT INSPECTION REPORT**

Project Name:	Mountain Valley Pipeline	Inspector:	John McCutcheon
Inspection Date:	Wednesday, July 25, 2018	Project Contact:	Brian Clauto, Tracy Hilbun
Spread:	Spread I	Weather (Wet/Dry/Rain):	Dry

STA	GE C	OF CONSTRUCTION: (Check all that apply)						
	Clea	aring Rough Grading X Trench Exca	avatio	n		$\boxtimes$	Pip	e Assembly, Testing & Installation
	Bac	kfilling and Grade Restoration Final Grading & Stabilizati	ion				Oth	ner:
			Yes	No	N/A			
1		e controls installed and implemented in accordance with the approved osion and sediment control plan and stormwater management plans?						
2	COI	e all control measures properly maintained in effective operating ndition in accordance with good engineering practices and, where plicable, manufacturer specifications?						
3	Are	eas of offsite sediment deposition were observed?	$\boxtimes$					
Co	mme	ents: This report is for an inspection at Bonbrook Mill Road MP 265.5.						
	1.	Waterbar above Bonbrook Mill Road eroded and is not discharging or	nto ur	ndist	urbed	area c	off the	e ROW.
	2.	Compost filter socks silt fence and check dams need maintenance. Fagged and are not level.	-ence	and	dam	holding	g trap	pped sediment. Filter socks have
	3.	Stabilization on trench spoil stockpiles is thin or absent.						
	4.	Sediment has been deposited in ditch and grass on either side of Bor	nbroo	k Mil	l Drive	e.		
Dea	dline	: Within 24 hours of receipt or as noted						_
cons	titute	nmended corrective action deadline date applies to all conditions noted on this re non-compliance and/or corrective actions are not completed by the deadline, oth ompliance on the above project.						
		fle R. Mc ather						
Iner	ecto	r Signature				Date	۵.	7-25-18



## PIPELINE SWPPP INSPECTION REPORT REQUEST FOR CORRECTIVE ACTION

Comment #	Regulatory Citation/Legal requirement <sup>1</sup>	Observation/Recommended Corrective Action					
1	(Va. Code §62.1- 44.15:31) (MVP Standards & Specifications for VA, p. 1) (9VAC 25-840- 60.A).	Observation: Waterbar eroded and discharging back onto ROW.  Recommended Corrective Action: Clean out and repair waterbar.					
2	(Va. Code §62.1- 44.15:31) (MVP Standards & Specifications for VA, p. 1) (9VAC 25-840- 60.A).	Observation: Compost filter socks silt fence and check dams need maintenance  Recommended Corrective Action: Clean out accumulated sediment in silt fence and check dams. Re-level sagging compost filter socks.					
3	(Va. Code §62.1- 44.15:31) (MVP Standards & Specifications for VA, p. 1) (9VAC 25-840- 40.2	Observation: Stabilization on stockpiles is thin or absent.  Recommended Corrective Action: Stabilize stockpiles.					
4	(Va. Code §62.1- 44.15:31) (MVP Standards & Specifications for VA, p. 1) (9VAC 25-880- 70.II.G.2.)	Observation: Sediment has been deposited in ditch and grass on either side of Bonbrook Mill Drive.  Recommended Corrective Action: Remove sediment and stabilize disturbed areas.					
Comments:							
recommended		ndline: Within 24 Hours of notice  The date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for					
pector Signa	ature: #L A	Date:					

<sup>&</sup>lt;sup>1</sup> Refers to applicable regulation found in the most recent publication of the State Water Control Law (Va. Code § 62.1-44.2 et seq.), Virginia Erosion and Sediment Control Regulations (9VAC25-840), the Virginia Stormwater Management Program (VSMP) Regulations (9VAC25-870), Annual Standards and Specifications for Erosion & Sediment Control (ESC) and Stormwater Management (SWM) for Mountain Valley Pipeline (MVP) LLC as revised June 2017...



## FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline Date: Wednesday, July 25, 2018



End of waterbar eroded, discharging downhill instead of off ROW. Repaired with straw bale.



Filter sock check dam loaded with sediment. Sediment in roadside ditch.



Silt fence loaded with sediment. Compost filter socks have sagged.



Stockpiles unstabilized.



Sediment in roadside ditch.