

## COMPLAINT INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis	
Inspection Date:	Monday, October 28, 2019	Project Contact:	Brian Clauto	
Spread H: Montgomery County	STA 12175+00 - 12200+00 ATWS 703, ATWS 704A, ATWS 1446 & ATWS 1375 MVP-MN-275/274	Weather (Wet/Dry/Rain):	Wet	

Spread H: Montgomery County			Rain):	W	Wet		
				_		_	
STAGE OF CONSTRUCT	TION: (Check all that apply)						
Clearing	Rough Grading	Trench Exca	avation	า			Pipe Assembly, Testing & Installation
☐ Backfilling and Grade Restoration ☐ Final Grading & Stabilizati			ion	n Other: <u>Dormant</u>			Other: Dormant
_				No			
	ed and implemented in accordance wi ent control plan and stormwater mana						
2 condition in accord	ssures properly maintained in effective lance with good engineering practices acturer specifications?			$\boxtimes$			
3 Areas of offsite sec	diment deposition were observed?						
Road area. The compla	stigation was conducted in response to aint describes sediment laden runoff in also describes low levels of turbidity to N.	mpacting Bradsha	aw Cre	eek a	and subs	sequ	ently the North Fork of the Roanoke
Observations:  1. At the time of i	inspection, there was no evidence of s	sediment dischar	ge from	m M\	√P ROV	V ont	to Bradshaw Road or into Bradshaw
Creek. See Fig	gures 2, 3, 4, 5 & 6.		•				
<ol><li>ECDs within the designed. See</li></ol>	ne MVP LOD and along the resources e Note #3.	s were installed p	er the	аррі	roved pl	ans a	and appeared to be functioning as
<ol><li>One maintena</li></ol>	nce item was found at STA 12179+50 discharged off ROW as a result.	) (see Figure 8).	P1 Sil	lt Fer	nce was	s und	lermined at that location, however no
		r downstream of t	the M\	VP cı	rossing	of Br	radshaw Creek (S-C21). See Figures
	ring along the Boanaka Vallay Bossur	roo Authority (DV)	D 1 1	N. 12 P.	00 11:55	. مام	imported during the increasing

Erosion occurring along the Roanoke Valley Resource Authority (RVRA) spur line was documented during the inspection. Discharge from these channels flows through the MVP ROW and into S-OO11. See Figure 7.

Comments: ROW inspected in Montgomery County from STA 12175+00 though STA 12200+00. The following resources were documented during the onsite complaint investigation: S-C21 (Bradshaw Creek) and S-OO11 (UNT to Bradshaw Creek).

STA 12179+50: P1 maintenance needed.

Recommended Corrective Action: Maintain and install all controls per the approved plans and PSS&S.

**Deadline:** Within 24-hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

anshall Willis

Date: 10/28/2019



## FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline Date: Monday, October 28, 2019

Fig. 1: **STA 12201+00** – Controls in place and functioning. Area stabilized with erosion fabric and seed.



Fig. 2: **STA 12190+75** – Bradshaw Road crossing. No evidence of sediment discharge from ROW. Controls in place and functioning.



Fig. 3: **Stream S-C21** – Looking upstream at Bradshaw Creek crossing towards Bradshaw Road. No evidence of sediment discharge from ROW. Controls in place and functioning.



Fig. 4: **Stream S-C21** – Looking downstream at Bradshaw Creek crossing. No evidence of sediment discharge from ROW. Controls in place and functioning.





## FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline Date: Monday, October 28, 2019

Fig. 5: **Stream S-OO11** – Looking downstream at stream S-OO11 from ROW. No sediment deposition observed. Controls in place and functioning.



Fig. 6: **Stream S-OO11** – Looking upstream at stream S-OO11 from ROW. No sediment deposition observed. Controls in place and functioning.



Fig. 7: **STA 12197+40** – Looking NE towards RVRA spur line from ROW. Erosion along channel and banks of rail line evident.



Fig. 8: **STA 12179+50** – P1 undermined. Maintenance needed

