

COMPLAINT INVESTIGATION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Thursday, August 12, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Franklin County	STA 12915+20 – 12924+12 MVP-RO-286	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- | | | | | |
|---|---|--|--|--|
| <input type="checkbox"/> Tree Felling | <input checked="" type="checkbox"/> Clearing/Grubbing | <input checked="" type="checkbox"/> Grading | <input type="checkbox"/> Trenching | <input type="checkbox"/> Stringing/Welding |
| <input type="checkbox"/> Lowering/Backfilling | <input type="checkbox"/> Final Restoration | <input type="checkbox"/> Temp. Stabilization | <input type="checkbox"/> Perm. Stabilization | <input type="checkbox"/> Dormant |

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Background: This investigation was conducted in response to a complaint of possible work in wetlands (IR#: 300539) received on August 10, 2021 for the MVP ROW at MP 244.5.

Landowner Concerns:

1. MVP construction crews working within OHWM of S-EF44 and W-EF44.

Observations:

1. At the time of inspection, there was no evidence of sediment discharge from MVP ROW.
2. All work was being performed in upland areas.
3. PPL crews installing ECDs in area and establishing the buffer for stream S-E44 and wetland W-E44 on north side of the resources.
4. Installed ECDs within the MVP LOD were per the approved plans and appeared to be functioning as designed.
5. Tetra-Tech surveyors onsite re-staking OHWM for S-E44 and W-E44.

Comments: No corrective actions were noted during this inspection.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Thursday, August 12, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, August 12, 2021

Figure 1: STA 12923+66 – PPL crews installing ECDs and establishing buffer for stream S-EF44 and wetland W-EF44.

BRG: 209°SW (T) LAT: 37.143152 LON: -80.138230 ±16ft ALT: 2665ft



Figure 2: STA 12923+66 – Looking south towards stream S-EF44 and wetland W-EF44.

BRG: 196°S (T) LAT: 37.143190 LON: -80.138372 ±16ft ALT: 2667ft



Figure 3: Stream S-EF44/Wetland W-EF44 – PPL crews installing ECDs and establishing buffer for resources.

BRG: 165°S (T) LAT: 37.143014 LON: -80.138490 ±16ft ALT: 2653ft



Figure 4: Stream S-EF44/Wetland W-EF44 – PPL crews installing ECDs and establishing buffer for resources.

BRG: 213°SW (T) LAT: 37.143008 LON: -80.138490 ±16ft ALT: 2629ft



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, August 12, 2021

Figure 5: Stream S-EF44/Wetland W-EF44 – PPL crews installing ECDs and establishing buffer for resources.

BRG: 145°SE (T) LAT: 37.143031 LON: -80.138480 ±16ft ALT: 2621ft



Figure 6: Stream S-EF44/Wetland W-EF44 – PPL crews installing ECDs and establishing buffer for resources.

BRG: 190°S (T) LAT: 37.143046 LON: -80.138319 ±16ft ALT: 2640ft



Figure 7: Stream S-EF44/Wetland W-EF44 – PPL crews installing ECDs and establishing buffer for resources.

BRG: 247°SW (T) LAT: 37.143017 LON: -80.138342 ±16ft ALT: 2647ft



Figure 8: STA 12922+52 – Controls in place and functioning properly above stream S-EF44. PPL crews actively installing ECDs and establishing buffer area.

BRG: 255°W (T) LAT: 37.127907 LON: -80.140405 ±39796ft ALT: 1413ft

