

## FIELD INSPECTION REPORT

<b>Project Name:</b>	Mountain Valley Pipeline	<b>Inspector:</b>	Marshall Willis
<b>Inspection Date:</b>	Friday, August 6, 2021	<b>Project Contact:</b>	Brian Clauto, Cory Chalmers
<b>Spread G: Giles County</b>	STA 11298+08 – 11356+18 MVP-GI-253.02 MVP-GI-256	<b>Weather:</b>	Dry

**ACTIVE STAGE OF CONSTRUCTION:** (Check all that apply)

- Tree Felling     
  Clearing/Grubbing     
  Grading     
  Trenching     
  Stringing/Welding  
 Lowering/Backfilling     
  Final Restoration     
  Temp. Stabilization     
  Perm. Stabilization     
  Other

- |    |   | Yes                                 | No                                  | N/A                      |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed?  | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: N/A.

**Recommended Corrective Action:** N/A

**Deadline:** N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

**Inspector Signature:** 

**Date:** Friday, August 6, 2021

## FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Friday, August 6, 2021

**Figure 1: STA 11299+00** – Controls in place and functioning properly.  
 BRG: 100°E (T) LAT: 37.296728 LON: -80.478602 ±32ft ALT: 2287ft



**Figure 2: STA 11317+00** – Controls in place and functioning properly.  
 BRG: 37°NE (T) LAT: 37.295694 LON: -80.476087 ±7237ft ALT: 2312ft



**Figure 3: Stream S-NN12** – Controls in place and functioning properly along stream S-NN12.  
 BRG: 237°SW (T) LAT: 37.300621 LON: -80.472870 ±98ft ALT: 2140ft



**Figure 4: STA 11346+00** – Controls in place and functioning properly.  
 BRG: 34°NE (T) LAT: 37.303949 LON: -80.468563 ±98ft ALT: 2087ft

