

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Tuesday, July 27, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread G: Giles County	STA 11158+12 – 11252+17 STA 10802+00 – 10820+00 MVP-GI-249.03 MVP-MLV-AR-25	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- | | | | | |
|--|--|---|---|---|
| <input type="checkbox"/> Tree Felling | <input type="checkbox"/> Clearing/Grubbing | <input type="checkbox"/> Grading | <input checked="" type="checkbox"/> Trenching | <input checked="" type="checkbox"/> Stringing/Welding |
| <input checked="" type="checkbox"/> Lowering/Backfilling | <input type="checkbox"/> Final Restoration | <input checked="" type="checkbox"/> Temp. Stabilization | <input type="checkbox"/> Perm. Stabilization | <input type="checkbox"/> Dormant |

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-NN17 and S-Z14.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: 

Date: Tuesday, July 27, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, July 27, 2021

Figure 1: STA 11227+00 – Controls in place and functioning properly.
 BRG: 142°SE (T) LAT: 37.329366 LON: -80.421533 ±16420ft ALT: 2010ft



Figure 2: STA 11245+00 – Controls in place and functioning properly.
 BRG: 151°SE (T) LAT: 37.310473 LON: -80.506968 ±12326ft ALT: 2127ft



Figure 3: STA 11210+00 – Controls in place and functioning properly.
 BRG: 305°NW (T) LAT: 37.302960 LON: -80.505797 ±32ft ALT: 2013ft



Figure 4: STA 11163+00 – Controls in place and functioning properly.
 BRG: 288°W (T) LAT: 37.311321 LON: -80.514494 ±16ft ALT: 1829ft

