

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Monday, July 26, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread G: Giles County Craig County	STA 11524+16 – 11528+00 STA 10971+74 – 10929+71 MVP-CR-258.02 MVP-GI-242.01	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- | | | | | |
|--|---|--|---|--|
| <input type="checkbox"/> Tree Felling | <input type="checkbox"/> Clearing/Grubbing | <input type="checkbox"/> Grading | <input checked="" type="checkbox"/> Trenching | <input type="checkbox"/> Stringing/Welding |
| <input checked="" type="checkbox"/> Lowering/Backfilling | <input checked="" type="checkbox"/> Final Restoration | <input type="checkbox"/> Temp. Stabilization | <input type="checkbox"/> Perm. Stabilization | <input type="checkbox"/> Dormant |

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-MN11.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: 

Date: Monday, July 26, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Monday, July 26, 2021

Figure 1: STA 10969+00 – Controls in place and functioning properly.
 BRG: 266°W (T) LAT: 37.327408 LON: -80.569155 ±164ft ALT: 2452ft



Figure 2: STA 10955+00 – Controls in place and functioning properly.
 BRG: 295°NW (T) LAT: 37.324559 LON: -80.588027 ±18789ft ALT: 2247ft



Figure 3: Stream S-MN11 – Controls in place and functioning properly.
 BRG: 337°NW (T) LAT: 37.333088 LON: -80.559416 ±5449ft ALT: 2992ft



Figure 4: STA 11527+00 – Controls in place and functioning properly.
 BRG: 57°NE (T) LAT: 37.329510 LON: -80.419994 ±16ft ALT: 2281ft

