

COMPLAINT INVESTIGATION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Thursday, July 15, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Franklin County	STA 13188+66 – 13195+79 MVP-FR-292.02	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- Tree Felling
 Clearing/Grubbing
 Grading
 Trenching
 Stringing/Welding
 Lowering/Backfilling
 Final Restoration
 Temp. Stabilization
 Perm. Stabilization
 Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Background: This investigation was conducted in response to a complaint (IR#: 300189) received on July 14, 2021 for the Dillons Mill and Adney Gap area near MP 249.7.

1. The complaint describes “muddy runoff pumped from MVP trenching” from “MVP trenching site in a field at the intersection of Dillons Mill and Adney Gap Road”.

Observations:

1. PPL crews actively trenching and lowering pipe in area. Groundwater present in open trench being pumped into sediment bags. Sediment bags were placed into a secondary straw bale dewatering structures allowing discharge to a well vegetated area off ROW.
2. Controls in place and functioning properly at the time of inspection.
3. No evidence of sediment discharge off ROW found during the inspection.

Comments:

1. ROW inspected in Franklin County from STA 13188+66 though STA 13195+79 near the intersection of Dillons Mill Road and Adney Gap Road.

Routine Maintenance: (72-Hour Deadline from Notification)

- N/A

Ineffective Controls: (24-Hour Deadline from Notification)

- N/A

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: *Marshall Willis*

Date: **Thursday, July 15, 2021**

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, July 15, 2021

Figure 1: STA 13190+00 – Trench filled with groundwater.

BRG: 129°SE (T) **LAT:** 37.124291 **LON:** -80.075984 ±32ft **ALT:** 1484ft



Figure 2: STA 13194+50 – Dewatering structure #1 on west side of the ROW. Pump hoses discharging into sediment bag inside of secondary dewatering structure.

BRG: 317°NW (T) **LAT:** 37.123209 **LON:** -80.075405 ±16ft **ALT:** 1417ft



Figure 3: STA 13194+50 – Dewatering structure #1 on west side of the ROW. Discharging onto well vegetated area. No sediment off ROW.

BRG: 283°W (T) **LAT:** 37.123267 **LON:** -80.075400 ±16ft **ALT:** 1431ft



Figure 4: STA 13194+50 – Dewatering structure #1 on west side of the ROW. Discharging onto well vegetated area. No sediment off ROW.

BRG: 64°NE (T) **LAT:** 37.123352 **LON:** -80.075688 ±164ft **ALT:** 1466ft



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, July 15, 2021

Figure 5: STA 13190+00 – Dewatering structure #2 on east side of the ROW. Pump hoses discharging into sediment bag inside of secondary dewatering structure.

BRG: 171°S (T) **LAT:** 37.124726 **LON:** -80.076312 ±16ft **ALT:** 1470ft



Figure 6: STA 13190+00 – Dewatering structure #2 on east side of the ROW. Discharging onto well vegetated area. No sediment off ROW.

BRG: 121°SE (T) **LAT:** 37.124722 **LON:** -80.076267 ±16ft **ALT:** 1469ft

