

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Tuesday, July 13, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread G: Giles County	STA 10656+00 – 10670+00 STA 10759+00 – 10798+83 MVP-GI-240	Weather:	Wet

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- Tree Felling
 Clearing/Grubbing
 Grading
 Trenching
 Stringing/Welding
 Lowering/Backfilling
 Final Restoration
 Temp. Stabilization
 Perm. Stabilization
 Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-SS4, S-Z9, S-Z7 and S-Z7-Braid.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: 

Date: Tuesday, July 13, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, July 13, 2021

Figure 1: STA 10669+00 – Controls in place and functioning properly.

BRG: 35°NE (T) LAT: 37.348699 LON: -80.671186 ±21272ft ALT: 1773ft



Figure 2: STA 10664+00 – Controls in place and functioning properly.

BRG: 309°NW (T) LAT: 37.352295 LON: -80.661218 ±11187ft ALT: 2237ft



Figure 3: STA 10774+00 – Controls in place and functioning properly.

BRG: 70°E (T) LAT: 37.343961 LON: -80.627679 ±6318ft ALT: 2171ft



Figure 4: STA 10788+00 – Controls in place and functioning properly.

BRG: 159°S (T) LAT: 37.343750 LON: -80.624143 ±98ft ALT: 1791ft

