

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Monday, June 28, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread G: Giles County	STA 11084+78 – 11158+12 MVP-GI-245.01 MVP-GI-249	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- Tree Felling
 Clearing/Grubbing
 Grading
 Trenching
 Stringing/Welding
 Lowering/Backfilling
 Final Restoration
 Temp. Stabilization
 Perm. Stabilization
 Dormant

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-IJ16-a.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Monday, June 28, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Monday, June 28, 2021

Figure 1: STA 11151+00 – Controls in place and functioning properly.
 BRG: 103°E (T) LAT: 37.312516 LON: -80.518535 ±16ft ALT: 2029ft



Figure 2: STA 11138+00 – Controls in place and functioning properly.
 BRG: 285°W (T) LAT: 37.312907 LON: -80.518180 ±15492ft ALT: 2143ft



Figure 3: STA 11124+00 – Controls in place and functioning properly.
 BRG: 279°W (T) LAT: 37.315474 LON: -80.526587 ±16ft ALT: 1946ft



Figure 4: STA 11087+00 – Controls in place and functioning properly.
 BRG: 263°W (T) LAT: 37.315434 LON: -80.538351 ±16ft ALT: 2171ft

