

FIELD INSPECTION REPORT

| | | | |
|-----------------------------------|--------------------------|-------------------------|-----------------------------|
| Project Name: | Mountain Valley Pipeline | Inspector: | Marshall Willis |
| Inspection Date: | Monday, August 23, 2021 | Project Contact: | Brian Clauto, Cory Chalmers |
| Spread G: Giles County | STA 10859+34 – 10930+00 | Weather: | Dry |

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- Tree Felling
 Clearing/Grubbing
 Grading
 Trenching
 Stringing/Welding
 Lowering/Backfilling
 Final Restoration
 Temp. Stabilization
 Perm. Stabilization
 Other

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-Y3, Y2 and S-A32.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: _____



Date: Monday, August 23, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Monday, August 23, 2021

Figure 1: STA 10859+34 – Controls in place and functioning properly.
 BRG: 310°NW (T) LAT: 37.337414 LON: -80.604308 ±16ft ALT: 2326ft



Figure 2: STA 10870+00 – Controls in place and functioning properly.
 BRG: 114°SE (T) LAT: 37.336352 LON: -80.601044 ±32ft ALT: 2448ft



Figure 3: STA 10872+00 – Controls in place and functioning properly.
 BRG: 47°NE (T) LAT: 37.336210 LON: -80.600754 ±948ft ALT: 2426ft



Figure 4: STA 10878+00 – Controls in place and functioning properly.
 BRG: 110°E (T) LAT: 37.336211 LON: -80.596361 ±541ft ALT: 2224ft

