

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Monday, August 16, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread G: Giles County	STA 11298+08 – 11356+18 MVP-GI-253.02 MVP-GI-256	Weather:	Rainy

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- Tree Felling
 Clearing/Grubbing
 Grading
 Trenching
 Stringing/Welding
 Lowering/Backfilling
 Final Restoration
 Temp. Stabilization
 Perm. Stabilization
 Other

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: N/A.

Ineffective Controls: *(24-Hour Deadline from Notification)*

- STA 10858+00 to 10859+00: Stabilize fill slope.
- STA 10857+00 to 10859+00: Stabilize fill slope.

Recommended Corrective Action: Maintain and install all controls per the approved PSS&S.

Deadline: Within 24-Hour of Notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Monday, August 16, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Monday, August 16, 2021

Figure 1: STA 10858+00 to 10859+00 – Stabilize fill slope.

BRG: 283°W (T) **LAT:** 37.337418 **LON:** -80.604522 ±16ft **ALT:** 2295ft



Figure 2: STA 10857+00 to 10859+00 – Stabilize fill slope.

BRG: 270°W (T) **LAT:** 37.337408 **LON:** -80.604686 ±16ft **ALT:** 2285ft



Figure 3: STA 10795+00 – Controls in place and functioning properly.

BRG: 172°S (T) **LAT:** 37.342533 **LON:** -80.622358 ±32ft **ALT:** 1991ft



Figure 4: STA 10791+00 – Controls in place and functioning properly.

BRG: 293°NW (T) **LAT:** 37.342735 **LON:** -80.622806 ±16ft **ALT:** 1900ft

