

## FIELD INSPECTION REPORT

<b>Project Name:</b>	Mountain Valley Pipeline	<b>Inspector:</b>	Marshall Willis
<b>Inspection Date:</b>	Friday, September 10, 2021	<b>Project Contact:</b>	Brian Clauto, Cory Chalmers
<b>Spread G: Craig County Montgomery County</b>	STA 11596+00 – 11619+00 STA 11978+54 – 11988+96 MVP-MN-258.04 MVP-MN-266	<b>Weather:</b>	Dry

**ACTIVE STAGE OF CONSTRUCTION:** (Check all that apply)

- Tree Felling     
  Clearing/Grubbing     
  Grading     
  Trenching     
  Stringing/Welding  
 Lowering/Backfilling     
  Final Restoration     
  Temp. Stabilization     
  Perm. Stabilization     
 Dormant

- |  | Yes                                 | No                                  | N/A                      |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed?  | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-OO6, S-RR13 and S-RR14.

**Recommended Corrective Action:** N/A

**Deadline:** N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

**Inspector Signature:** 

**Date:** Friday, September 10, 2021

## FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Friday, September 10, 2021

**Figure 1: STA 11598+00** – Controls in place and functioning properly.

BRG: 340°N (T) LAT: 37.314445 LON: -80.406517 ±16ft ALT: 1957ft



11598

**Figure 2: STA 11616+00** – Controls in place and functioning properly. Area stabilized with straw.

BRG: 46°NE (T) LAT: 37.313664 LON: -80.401906 ±16ft ALT: 1927ft



11616

**Figure 3: Stream S-RR13** – Controls in place and functioning properly along Craig Creek.

BRG: 36°NE (T) LAT: 37.314177 LON: -80.401711 ±16902ft ALT: 1913ft



A-0013

**Figure 4: STA 11960+00** – Controls in place and functioning properly.

BRG: 116°SE (T) LAT: 37.270205 LON: -80.315308 ±7011ft ALT: 1610ft



11980