

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Wednesday, September 8, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread G: Giles County Craig County	STA 11353+21 – 11526+00 MVP-CR-258.02 MVP-GI-256.02	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- Tree Felling
 Clearing/Grubbing
 Grading
 Trenching
 Stringing/Welding
 Lowering/Backfilling
 Final Restoration
 Temp. Stabilization
 Perm. Stabilization
 Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-KL43, W-CD12, S-OO14, S-OO13, S-OO12, S-PP1, S-PP2, S-PP3 and S-PP4.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: 

Date: Wednesday, September 8, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, September 8, 2021

Figure 1: STA 11526+00 – Controls in place and functioning properly.

BRG: 78°E (T) LAT: 37.329488 LON: -80.420349 ±16ft ALT: 2256ft



11526

Figure 2: STA 11514+00 – Controls in place and functioning properly.

BRG: 246°SW (T) LAT: 37.327627 LON: -80.424024 ±16ft ALT: 2273ft



11514

Figure 3: STA 11425+00 – Controls in place and functioning properly.

BRG: 257°W (T) LAT: 37.314903 LON: -80.447818 ±32ft ALT: 2298ft



11425

Figure 4: STA 11413+00 – Controls in place and functioning properly.

BRG: 230°SW (T) LAT: 37.312899 LON: -80.451152 ±16ft ALT: 2344ft



11413