



Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant		
Inspection Date:	Monday, October 18, 2021	Project Contact:	Brian Clauto		
Spread G: Giles	AR 251.01 10859-10930 11230-11255 ATWS1360, 1332, 1347, 1331, 471	Weather:	Dry		

Spread G: Giles	11230-11255 ATWS1360, 1332, 1347, 1	1331, 471	Weather:		Dry			
ACTIVE STAGE OF CON	ISTRUCTION: (Check all tha	at apply)						
☐ Tree Felling	☐ Clearing/Grubbing	☐ Gra	ding	☐ Trenc	hing		Strir	nging/Welding
☐ Lowering/Backfilling	g 🔲 Final Grading	⊠ Tem	np. Stabilization	☐ Perm.	Stabilization	\boxtimes	Dor	mant
						Yes	No	N/A
	Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?							
	Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?							
3. Areas o	Areas of offsite sediment deposition observed?						\boxtimes	
 <u>Comments:</u> Inspected the following resources: S-A32, S-Y3, S-Y2, S-RR2, W-RR1b <u>ECD's were in place and functioning above the designated crossing for active construction.</u> Routine Maintenance: (<u>72-Hour Deadline from Notification</u>) N/A Ineffective Controls: (<u>24-Hour Deadline from Notification</u>) N/A Recommended Corrective Action: N/A 								

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: _____

Date: Monday, October 18, 2021



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Figure 1: St 10859 ECD's are in place and area has been stabilized.




Figure 2: Designated crossing S-A32, ECD's are in place.

Date: Monday, October 18, 2021



Figure 3: ATWS 1360 area is stabilized



• Figure 4: St 10899 area is stabilized and ECD's are in place.

