

## FIELD INSPECTION REPORT

<b>Project Name:</b>	Mountain Valley Pipeline	<b>Inspector:</b>	Marshall Willis
<b>Inspection Date:</b>	Wednesday, October 13, 2021	<b>Project Contact:</b>	Brian Clauto, Cory Chalmers
<b>Spread G: Montgomery County</b>	STA 11669+00 – 11768+00 MVP-MLV-AR-26	<b>Weather:</b>	Wet

**ACTIVE STAGE OF CONSTRUCTION:** (Check all that apply)

- Tree Felling     
  Clearing/Grubbing     
  Grading     
  Trenching     
  Stringing/Welding  
 Lowering/Backfilling     
  Final Restoration     
  Temp. Stabilization     
  Perm. Stabilization     
 Dormant

- |  | Yes                                 | No                                  | N/A                      |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed?  | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

**Comments:** Inspected the following resources: S-IJ12, W-MN7, W-KL51-PSS, S-KL55, W-KL49-PEM, W-KL50 and W-KL48-PSS-1.

**Recommended Corrective Action:** N/A

**Deadline:** N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

**Inspector Signature:** 

**Date:** Wednesday, October 13, 2021

## FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Wednesday, October 13, 2021

**Figure 1: STA 11682+00** – Controls in place and functioning properly. Area stabilized with straw.  
 BRG: 332°NW (T) LAT: 37.300374 LON: -80.392584 ±16ft ALT: 2576ft



**Figure 2: STA 11709+00** – Controls in place and functioning properly. Area stabilized with straw.  
 BRG: 111°E (T) LAT: 37.296546 LON: -80.384996 ±32ft ALT: 2379ft



**Figure 3: STA 11720+00** – Controls in place and functioning properly. Area stabilized with straw.  
 BRG: 318°NW (T) LAT: 37.295088 LON: -80.381955 ±98ft ALT: 2250ft



**Figure 4: STA 11751+00** – Controls in place and functioning properly. Area stabilized with straw.  
 BRG: 288°W (T) LAT: 37.288736 LON: -80.373423 ±16092ft ALT: 2037ft

