

FIELD INSPECTION REPORT

| | | | |
|-----------------------------------|---|-------------------------|-----------------------------|
| Project Name: | Mountain Valley Pipeline | Inspector: | Marshall Willis |
| Inspection Date: | Wednesday, October 6, 2021 | Project Contact: | Brian Clauto, Cory Chalmers |
| Spread G: Giles County | STA 11158+37 – 11230+00 MVP-MLV-AR-25 MVP-GI-249.01/.03 | Weather: | Wet |

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- Tree Felling
 Clearing/Grubbing
 Grading
 Trenching
 Stringing/Welding
 Lowering/Backfilling
 Final Restoration
 Temp. Stabilization
 Perm. Stabilization
 Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-NN17

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: 

Date: Wednesday, October 6, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, October 6, 2021

Figure 1: STA 11227+00 – Controls in place and functioning properly.
 BRG: 121°SE (T) LAT: 37.310555 LON: -80.516159 ±33914ft ALT: 1814ft



Figure 2: STA 11219+00 – Controls in place and functioning properly.
 BRG: 273°W (T) LAT: 37.301544 LON: -80.504047 ±16ft ALT: 2069ft



Figure 3: STA 11191+00 – Controls in place and functioning properly.
 BRG: 111°E (T) LAT: 37.306601 LON: -80.509923 ±98ft ALT: 1720ft



Figure 4: STA 11163+00 – Controls in place and functioning properly.
 BRG: 288°W (T) LAT: 37.311478 LON: -80.514426 ±98ft ALT: 1862ft

