



Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant		
Inspection Date:	Tuesday, September 21, 2021	Project Contact:	Brian Clauto		
Spread G: Giles	St10883+33, 10859+78, 10759- 10798 ATWS1056, 1334, 469, 466, 1360, 1332, 1333 AR GI 241.02	Weather:	Rainy		

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)												
	☐ Tree Felling ☐ Clearing/Gru		Clearing/Grubbin	ng 🖂	g 🗵 Grading			☐ Trenching		Stri	nging/Welding	
	Lowering/E	vering/Backfilling Final Grading Temp. Stabilization Perm. Stabilization						Dormant				
										Yes	No	N/A
	1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?											
	2.	Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?										
	Areas of offsite sediment deposition observed?										\boxtimes	
 Comments: Inspected the following resources: S-Y2, S-A32, S-SS4, S-Z9, S-Z7 _ECD's were in place and functioning above the designated crossing for active construction. Sediment removal has been completed on S-Y2 where access was approved. Routine Maintenance: (72-Hour Deadline from Notification) N/A Ineffective Controls: (24-Hour Deadline from Notification) N/A Recommended Corrective Action: N/A 												

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: _____

Date: Tuesday, September 21, 2021



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline Date: Tuesday, September 21, 2021

<u>Figure 1</u>: Designated crossing S-Y2, ECD's are in place and functioning for active construction.



Figure 2: Designated crossing S-32, ECD's are in place and functioning.



 <u>Figure 3</u>: Designated crossing S-G35, ECD's are in place and functioning.



<u>Figure 4</u>: Designated crossing S-S4, ECD's are in place and functioning.

