

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Thursday, September 16, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread G: Giles County	STA 11254+88 – 11353+21 MVP-GI-253.02	Weather:	Wet

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☒ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-NN11, S- NN12, W-MM10, S-MM17 and S-MM18.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: Thursday, September 16, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, September 16, 2021

Figure 1: STA 11285+00 – Controls in place and functioning properly. Area stabilized with straw.

BRG: 51°NE (T) LAT: 37.264609 LON: -80.461383 ±20449ft ALT: 2094ft



Figure 2: STA 11267+00 – Controls in place and functioning properly. Area stabilized with straw.

BRG: 229°SW (T) LAT: 37.296407 LON: -80.490090 ±16ft ALT: 2261ft



Figure 3: STA 11304+00 – Controls in place and functioning properly. Area stabilized with straw.

BRG: 90°E (T) LAT: 37.283770 LON: -80.488809 ±18024ft ALT: 2046ft



Figure 4: STA 11313+00 – Controls in place and functioning properly. Area stabilized with straw.

BRG: 11°N (T) LAT: 37.273157 LON: -80.473412 ±19301ft ALT: 2217ft

