

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Tuesday, September 14, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread G: Giles County	STA 11158+37 – 11230+00 MVP-MLV-AR-25 MVP-GI-249.01/.03	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- Tree Felling
 Clearing/Grubbing
 Grading
 Trenching
 Stringing/Welding
 Lowering/Backfilling
 Final Restoration
 Temp. Stabilization
 Perm. Stabilization
 Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-NN17.

Routine Maintenance: (72-Hour Deadline from Notification)

- STA 11165+72: Re-stabilize stockpile.

Recommended Corrective Action: Maintain and install all controls per the approved PSS&S.

Deadline: Within 72-Hour of Notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Tuesday, September 14, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, September 14, 2021

Figure 1: STA 11228+00 – Controls in place and functioning properly.

BRG: 139°SE (T) LAT: 37.265594 LON: -80.462867 ±19527ft ALT: 1810ft



11228

Figure 2: STA 11208+00 – Controls in place and functioning properly.

BRG: 328°NW (T) LAT: 37.303235 LON: -80.506261 ±16ft ALT: 1965ft



11208

Figure 3: STA 11197+00 – Controls in place and functioning properly.

BRG: 281°W (T) LAT: 37.306384 LON: -80.508404 ±98ft ALT: 2105ft



11197

Figure 4: STA 11165+72 – Re-stabilize stockpile.

BRG: 227°SW (T) LAT: 37.310945 LON: -80.513967 ±16ft ALT: 1830ft



ReStabilize_stockpile 72hr

11165+72