

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Monday, November 1, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread G: Giles County	STA 10674+92 – 10759+05 MVP-GI-241.01/04	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- Tree Felling
 Clearing/Grubbing
 Grading
 Trenching
 Stringing/Welding
 Lowering/Backfilling
 Final Restoration
 Temp. Stabilization
 Perm. Stabilization
 Dormant

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-G30, S-G32, S-G33, W-Z11 and S-G35.

Ineffective Controls: (24-Hour Deadline from Notification)

- ATWS 1390: Stabilization needed.
- STA 10707+25: Stabilization needed.
- STA 10676+15: Stabilization needed.

Recommended Corrective Action: Maintain and install all controls per the approved PSS&S.

Deadline: Within 24-Hour of Notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: 

Date: Monday, November 1, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Monday, November 1, 2021

Figure 1: ATWS 1390 – Stabilization needed.

BRG: 349°N (T) **LAT:** 37.331412 **LON:** -80.676935 ±13123ft **ALT:** 1735ft



Stabilize 24hr

Atws 1390

Figure 2: STA 10707+25 – Stabilization needed.

BRG: 129°SE (T) **LAT:** 37.348258 **LON:** -80.649036 ±32ft **ALT:** 2351ft



Stabilize 24hr

10707+25

Figure 3: STA 10676+15 –Stabilization needed.

BRG: 73°E (T) **LAT:** 37.350402 **LON:** -80.659427 ±16ft **ALT:** 2110ft



Stabilize end of RCE 24hr

10676+15

Figure 4: STA 10728+00 – Controls in place and functioning properly. Area stabilized with straw.

BRG: 99°E (T) **LAT:** 37.347101 **LON:** -80.642854 ±32ft **ALT:** 2367ft



10728