

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Thursday, December 2, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread G: Giles County	STA 10656+00 – 10675+13 Laydown Yard 028/029 MVP-GI-240 MVP-GI-238.01	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- Tree Felling
 Clearing/Grubbing
 Grading
 Trenching
 Stringing/Welding
 Lowering/Backfilling
 Final Restoration
 Temp. Stabilization
 Perm. Stabilization
 Dormant

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: N/A.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: 

Date: Thursday, December 2, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, December 2, 2021

Figure 1: Laydown Yard 029 – Controls in place and functioning properly.

BRG: 27°NE (T) **LAT:** 37.333986 **LON:** -80.803010 ±16ft **ALT:** 1564ft



Figure 2: STA 10673+00 – Controls in place and functioning properly. Area stabilized with straw.

BRG: 87°E (T) **LAT:** 37.350623 **LON:** -80.660672 ±98ft **ALT:** 2123ft



Figure 3: STA 10665+00 – Controls in place and functioning properly. Area stabilized with straw

BRG: 299°NW (T) **LAT:** 37.353081 **LON:** -80.661320 ±32ft **ALT:** 2255ft



Figure 4: Laydown Yard 029 – Controls in place and functioning properly.

BRG: 193°S (T) **LAT:** 37.363271 **LON:** -80.676799 ±98ft **ALT:** 1814ft

