

## COMPLAINT INVESTIGATION REPORT

<b>Project Name:</b>	Mountain Valley Pipeline	<b>Inspector:</b>	Marshall Willis
<b>Inspection Date:</b>	Tuesday, November 30, 2021	<b>Project Contact:</b>	Brian Clauto, Cory Chalmers
<b>Spread H: Roanoke County</b>	STA 12862+00 – 12866+36	<b>Weather:</b>	Dry

**ACTIVE STAGE OF CONSTRUCTION:** (Check all that apply)

- Tree Felling     
  Clearing/Grubbing     
  Grading     
  Trenching     
  Stringing/Welding  
 Lowering/Backfilling     
  Final Restoration     
  Temp. Stabilization     
  Perm. Stabilization     
 Dormant

- |  | Yes                                 | No                                  | N/A                      |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed?  | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

**Background:** This investigation was conducted in response to a complaint (IR#: 301677) of possible fill placed in wetlands received on November 30, 2021 for the MVP ROW at approx. MP 243.4. Complaint contained pictures of woody debris stockpiled within the ROW at approx. STA 12865+00 and adjacent to ATWS 1326.

**Landowner Concerns:**

1. Fill material placed within the delineated wetland resource.

**Observations:**

1. The woody debris pile or "fill" pile of concern was located at approximate STA 12865+00.
2. The woody debris pile was located outside of Wetland W-AB3-PEM-2 (STA 12854+57). No impacts were observed to the resource.
3. Survey crews were onsite during the inspection re-staking the wetland delineation for W-AB3-PEM-2.
4. Installed ECDs within the MVP LOD were per the approved plans and appeared to be functioning as designed.

**Comments:** No corrective actions were noted during this inspection.

**Recommended Corrective Action:** N/A

**Deadline:** N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

**Inspector Signature:** 

**Date:** Tuesday, November 30, 2021

## FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Tuesday, November 30, 2021

**Figure 1: STA 12865+00** – Looking W towards Wetland W-AB3-PEM-2 from edge of disturbance. Note survey crews re-staking delineation of wetland with pink flags.

**BRG:** 274°W (T) **LAT:** 37.155671 **LON:** -80.129255 ±164ft **ALT:** 2681ft



**Figure 2: STA 12865+20** – Looking NW towards Wetland W-AB3-PEM-2. Woody debris stockpile is located within the LOD and outside the boundaries of Wetland W-AB3-PEM-2.

**BRG:** 297°NW (T) **LAT:** 37.155491 **LON:** -80.129130 ±16ft **ALT:** 2623ft



**Figure 3: STA 12865+00** – Looking W towards Wetland W-AB3-PEM-2 from edge of disturbance. No impacts were observed to the resource.

**BRG:** 268°W (T) **LAT:** 37.155555 **LON:** -80.129011 ±98ft **ALT:** 2697ft



**Figure 4: Wetland W-AB3-PEM-2** – Looking S towards debris pile from Wetland W-AB3-PEM-2. No impacts were observed to the resource.

**BRG:** 165°S (T) **LAT:** 37.155663 **LON:** -80.129417 ±16ft **ALT:** 2605ft

