



Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant		
Inspection Date:	Monday, November 29, 2021	Project Contact:	Brian Clauto		
Spread G: Giles	St11494 St10656+76-10712+41 St10700-10691+21 AR GI240, 241.01, 241 ATWS 1390, 1391, 816	Weather:	Dry		

			3 1390, 1391, 816										
ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)													
	Tree Felling	Felling Clearing/Grubbing Grading Trenching		Trenching		Stri	nging/Welding						
	Lowering/Backfilling	/Backfilling \square Final Grading \square Temp. Stabilization \square Perm. Stabilization \boxtimes Do						Dor	mant				
									Yes	No	N/A		
	Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?												
		Are all control measures properly maintained in effective operating condition in accordance											
	· ·												
:	Comments: Inspected										7		
Routine Maintenance: (<u>72-Hour Deadline</u> from Notification)													
- N/A													
Ineffective Controls: (<u>24-Hour Deadline</u> from Notification) - N/A													
Recommended Corrective Action: N/A													
											_		

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: _____

Date: Monday, November 29, 2021



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline <u>Date</u>: Monday, November 29, 2021

Figure 1. Designated crossing S-PP1, ECD's are in place.



Figure 2: Designated crossing S-G33, ECD's are in place.



Figure 3: Designated crossing S-G32, ECD's are in place.



Figure 4: St10691+21 ECD's are in place.

