

## FIELD INSPECTION REPORT

<b>Project Name:</b>	Mountain Valley Pipeline	<b>Inspector:</b>	Marshall Willis
<b>Inspection Date:</b>	Monday, November 8, 2021	<b>Project Contact:</b>	Brian Clauto, Cory Chalmers
<b>Spread G: Giles County</b>	STA 11098+00 – 11158+12 MVP-GI-245.02 MVP-GI-249	<b>Weather:</b>	Dry

**ACTIVE STAGE OF CONSTRUCTION:** (Check all that apply)

- Tree Felling     
  Clearing/Grubbing     
  Grading     
  Trenching     
  Stringing/Welding  
 Lowering/Backfilling     
  Final Restoration     
  Temp. Stabilization     
  Perm. Stabilization     
 Dormant

- |    |   | Yes                                 | No                                  | N/A                      |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed?  | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

**Comments:** Inspected the following resources: N/A

**Ineffective Controls:** (24-Hour Deadline from Notification)

- STA 11146+00: Stabilization needed.

**Recommended Corrective Action:** Maintain and install all controls per the approved PSS&S.

**Deadline:** Within 24-Hour of Notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

**Inspector Signature:**



**Date:** Monday, November 8, 2021

## FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Monday, November 8, 2021

**Figure 1: STA 11104+00** – Controls in place and functioning properly. Area stabilized with straw.

BRG: 73°E (T) LAT: 37.313563 LON: -80.532316 ±32ft ALT: 1997ft



**Figure 2: STA 11115+00** – Controls in place and functioning properly. Area stabilized with straw.

BRG: 111°E (T) LAT: 37.315593 LON: -80.529924 ±3576ft ALT: 2148ft



**Figure 3: STA 11146+15** –Stabilization needed.

BRG: 197°S (T) LAT: 37.313019 LON: -80.520078 ±16ft ALT: 2146ft



**Figure 4: STA 11151+00** – Controls in place and functioning properly. Area stabilized with straw.

BRG: 107°E (T) LAT: 37.301767 LON: -80.506437 ±17165ft ALT: 2034ft

