

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Monday, December 6, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread G: Giles County	STA 11254+88 – 11298+29 MVP-GI-253.02	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- Tree Felling
 Clearing/Grubbing
 Grading
 Trenching
 Stringing/Welding
 Lowering/Backfilling
 Final Restoration
 Temp. Stabilization
 Perm. Stabilization
 Dormant

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-MM18, W-MM10 and S-MM17.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: _____



Date: Monday, December 6, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Monday, December 6, 2021

Figure 1: STA 11297+00 – Controls in place and functioning properly. Area stabilized with straw
BRG: 259°W (T) LAT: 37.296326 LON: -80.479501 ±164ft ALT: 1950ft



Figure 2: STA 11284+00 – Controls in place and functioning properly. Area stabilized with straw
BRG: 72°E (T) LAT: 37.295938 LON: -80.484098 ±98ft ALT: 2120ft



Figure 3: STA 11273+00 – Controls in place and functioning properly. Area stabilized with straw
BRG: 84°E (T) LAT: 37.296367 LON: -80.488366 ±16ft ALT: 2285ft



Figure 4: STA 11256+00 – Controls in place and functioning properly. Area stabilized with straw
BRG: 122°SE (T) LAT: 37.296724 LON: -80.493480 ±32ft ALT: 1961ft

