



Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Monday, December 6, 2021	Project Contact:	Brian Clauto
Spread G: Giles	St11296-11255 AR GI253.02	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)												
	Tree Felling	g		Clearing/Grubbing		Grading		Trenching		Strin	nging/Welding	
	Lowering/E	vering/Backfilling   Final Grading   Temp. Stabilization   Pe		Perm. Stabilization	□ Dormant							
									Yes	No	N/A	
Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?												
	Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?								$\boxtimes$			
	3.	3. Areas of offsite sediment deposition observed?							$\boxtimes$			
<ul> <li>Comments: Inspected the following resources: S-MM18, W-RR1b, W-MM10, P-MM2</li> <li>_ECD's were in place and functioning above the designated crossing.</li> <li>Crews were on site preparing AR GI 242.01.</li> <li>Routine Maintenance: (72-Hour Deadline from Notification)         <ul> <li>N/A</li> </ul> </li> <li>Ineffective Controls: (24-Hour Deadline from Notification)         <ul> <li>N/A</li> </ul> </li> <li>Recommended Corrective Action: N/A</li> </ul>												
Deadline: N/A  The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.  Inspector Signature:												
Inspector Signature:												

Monday, December 6, 2021

Date:

## FIELD INSPECTION PHOTO LOG



**Project Name:** Mountain Valley Pipeline

Date: Monday, December 6, 2021

Figure 1. Designated crossing S-MM18, ECD's are in place.



Figure 2: Designated crossing W-RR1B, ECD's are in place.



Figure 3: St11265+41 area is stabilized and ECD's are in place.



Figure 4: St11265+41 area is stabilized and ECD's are in place

