



Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant		
Inspection Date:	Wednesday, February 9, 2022	Project Contact:	Brian Clauto		
Spread G: Giles	St11025-11064 ATWS 1146, 1145, 1465 AR-GI 244	Weather:	Dry		

GII	es		AR-G	1 244								
ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)												
	Tree Felling	☐ Clearing/Grubbing ☐ Grading ☐ Trenching		Trenching		Stri	nging/Welding					
	Lowering/Bac	Backfilling \square Final Grading \square Temp. Stabilization \square Perm. Stabilization				n 🗵 Dormant						
										Yes	No	N/A
	7	Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?								\boxtimes		
		Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?								\boxtimes		
	3. A	reas of o	ffsite	sediment deposition of	bserve	ed?					\boxtimes	
 <u>Comments:</u> Inspected the following resources: S-IJ 18, S-IJ19, S-IJ16b ECD's were in place and functioning at the designated crossings. 												
Routine Maintenance: (<u>72-Hour Deadline</u> from Notification) - N/A												
Ineffective Controls: (24-Hour Deadline from Notification) - N/A												
Recommended Corrective Action: N/A												

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:

Date: Wednesday, February 9, 2022

FIELD INSPECTION PHOTO LOG



Project Name: Mountain Valley Pipeline

Date: Wednesday, February 9, 2022

<u>Figure 1</u>: Designated crossing S-IJ19, ESC's are in place and functioning.



Figure 2: St 11044+71, ESC controls were in place.



 <u>Figure 3</u>: Designated crossing S-IJ16b, ESC's are in place and functioning.



Figure 4: St 11057, ECD's are in place and functioning.

