

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Monday, January 31, 2022	Project Contact:	Brian Clauto, Cory Chalmers
Spread G: Giles County	STA 10656+00 – 10711+00 MVP-GI-240 MVP-GI-241.01/241.04	Weather:	Snow

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- Tree Felling
 Clearing/Grubbing
 Grading
 Trenching
 Stringing/Welding
 Lowering/Backfilling
 Final Restoration
 Temp. Stabilization
 Perm. Stabilization
 Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-G30, S-G29 and S-G32.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: 

Date: Monday, January 31, 2022

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Monday, January 31, 2022

Figure 1: STA 10656+00 – Controls in place and functioning properly.

BRG: 73°E (T) **LAT:** 37.352936 **LON:** -80.663591 ±13421ft **ALT:** 2242ft



10656

Figure 2: STA 10661+00 – Controls in place and functioning properly.

BRG: 126°SE (T) **LAT:** 37.353408 **LON:** -80.662035 ±10429ft **ALT:** 2186ft



10661

Figure 3: STA 10699+00 – Controls in place and functioning properly.

BRG: 142°SE (T) **LAT:** 37.348760 **LON:** -80.651932 ±213ft **ALT:** 2084ft



10699

Figure 4: STA 10693+00 – Controls in place and functioning properly.

BRG: 257°W (T) **LAT:** 37.349569 **LON:** -80.653743 ±32ft **ALT:** 1995ft



10693