



Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant		
Inspection Date:	Monday, January 31, 2022	Project Contact:	Brian Clauto		
Spread G: Giles	St10710-10696+73 ATWS 1390, 1391 AR-GI 241.01	Weather:	Wet		

Giles			S 1390, 1391 I 241.01		Weather:		Wet			
ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)										
☐ Tree Felling			Clearing/Grubbing		Grading		Trenching		Stri	nging/Welding
☐ Lowering/Ba	ckfilling		Final Grading		Temp. Stabilization		Perm. Stabilization	ı 🗵	Dor	rmant
								Yes	No	N/A
	Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?					\boxtimes				
	Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?						\boxtimes			
3. A	Areas of o	offsite	sediment deposition o	bserve	d?				\boxtimes	
 <u>Comments:</u> Inspected the following resources: S-G33, S-AB13, S-AB14, S-G32 ECD's were in place and functioning at the designated crossings. 										
Routine Maintenance: (<u>72-Hour Deadline</u> from Notification) - N/A										
Ineffective Controls: (<u>24-Hour Deadline</u> from Notification) - N/A										
Recommended Corrective Action: N/A										

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: ____

Date: Monday, January 31, 2022

FIELD INSPECTION PHOTO LOG



<u>Project Name</u>: Mountain Valley Pipeline <u>Date</u>: Monday, January 31, 2022

Figure 1: ESC controls were snow covered near St 10710 above stream S-G33.



Figure 2: St 10705+34, ESC controls were in place.



 <u>Figure 3</u>: Designated stream crossing S-G32, ESC controls were in place.



Figure 4: ECD's in place at St 10696+73.

