

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Tuesday, January 11, 2022	Project Contact:	Brian Clauto, Cory Chalmers
Spread G: Giles County	STA 10929+00 – 10972+00 STA 11167+00 – 11227+00 MVP-MLV-AR-25 MVP-GI-249.01 MVP-GI-241.02	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- | | | | | |
|---|--|--|--|---|
| <input type="checkbox"/> Tree Felling | <input type="checkbox"/> Clearing/Grubbing | <input type="checkbox"/> Grading | <input type="checkbox"/> Trenching | <input type="checkbox"/> Stringing/Welding |
| <input type="checkbox"/> Lowering/Backfilling | <input type="checkbox"/> Final Restoration | <input type="checkbox"/> Temp. Stabilization | <input type="checkbox"/> Perm. Stabilization | <input checked="" type="checkbox"/> Dormant |

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-MN11.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: 

Date: Tuesday, January 11, 2022

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, January 11, 2022

Figure 1: MVP-GI-242.01 – Controls in place and functioning properly along access road.
BRG: 140°SE (T) **LAT:** 37.332773 **LON:** -80.560607 ±16ft **ALT:** 3018ft



Figure 2: STA 10970+00 – Controls in place and functioning properly. Area stabilized with straw.
BRG: 305°NW (T) **LAT:** 37.327106 **LON:** -80.570319 ±16ft **ALT:** 2452ft



Figure 3: STA 10961+00 – Controls in place and functioning properly.
BRG: 307°NW (T) **LAT:** 37.327940 **LON:** -80.572925 ±16ft **ALT:** 2308ft



Figure 4: STA 10940+00 – Controls in place and functioning properly. Area stabilized with straw.
BRG: 189°S (T) **LAT:** 37.330028 **LON:** -80.579988 ±16ft **ALT:** 2282ft

