

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Tuesday, January 11, 2022	Project Contact:	Brian Clauto
Spread G: Giles	ST1127-11170 ATWS 1464, 1370, 1370A, 1347 AR GI 249.01, 025	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- Tree Felling
 Clearing/Grubbing
 Grading
 Trenching
 Stringing/Welding
 Lowering/Backfilling
 Final Grading
 Temp. Stabilization
 Perm. Stabilization
 Dormant

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

▪ **Comments:** Inspected the following resources: N/A


Routine Maintenance: (72-Hour Deadline from Notification)
- N/A

Ineffective Controls: (24-Hour Deadline from Notification)
- N/A

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: _____  _____

Date: Tuesday, January 11, 2022

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, January 11, 2022

<p>▪ Figure 1: ATWS 1370, ESC's in place.</p> <div style="border: 1px solid black; padding: 5px; margin-bottom: 5px;"> <p style="text-align: center; background-color: #003366; color: white; margin: 0;">West Elevation</p> <p style="text-align: center; background-color: #e0e0e0; margin: 0;">☉ 79°E (T) ☉ 37°18'11"N, 80°30'14"W ±16ft ▲ 1999ft</p>  <p style="text-align: right; font-size: small;">Atws 1370</p> </div>	<p>▪ Figure 2: ATWS 1464, ESC's in place.</p> <div style="border: 1px solid black; padding: 5px; margin-bottom: 5px;"> <p style="text-align: center; background-color: #003366; color: white; margin: 0;">South East Elevation</p> <p style="text-align: center; background-color: #e0e0e0; margin: 0;">☉ 332°NW (T) ☉ 37°18'35"N, 80°30'52"W ±16ft ▲ 1867ft</p>  <p style="text-align: right; font-size: small;">Atws 1464</p> </div>
<p>▪ Figure 3: St1194+57 ESC's are in place and functioning.</p> <div style="border: 1px solid black; padding: 5px; margin-bottom: 5px;"> <p style="text-align: center; background-color: #003366; color: white; margin: 0;">East Elevation</p> <p style="text-align: center; background-color: #e0e0e0; margin: 0;">☉ 277°W (T) ☉ 37°18'22"N, 80°30'31"W ±16ft ▲ 2052ft</p>  <p style="text-align: right; font-size: small;">1194+57</p> </div>	<p>▪ Figure 4: St11215 ESC's are in place and functioning.</p> <div style="border: 1px solid black; padding: 5px; margin-bottom: 5px;"> <p style="text-align: center; background-color: #003366; color: white; margin: 0;">East Elevation</p> <p style="text-align: center; background-color: #e0e0e0; margin: 0;">☉ 276°W (T) ☉ 37°18'5"N, 80°30'16"W ±32ft ▲ 2066ft</p>  <p style="text-align: right; font-size: small;">11215</p> </div>