

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Wednesday, February 9, 2022	Project Contact:	Brian Clauto, Cory Chalmers
Spread G: Giles County	STA 11023+80 – 11151+27 MVP-GI-244 MVP-GI-249	Weather:	Wet

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- Tree Felling
 Clearing/Grubbing
 Grading
 Trenching
 Stringing/Welding
 Lowering/Backfilling
 Final Restoration
 Temp. Stabilization
 Perm. Stabilization
 Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-IJ19, S-IJ18, S-IJ17 and S-IJ16-B.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: 

Date: Wednesday, February 9, 2022

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, February 9, 2022

Figure 1: STA 11068+00 – Controls in place and functioning properly.
 BRG: 307°NW (T) LAT: 37.267910 LON: -80.471223 ±16535ft ALT: 2192ft



11068

Figure 2: STA 11081+00 – Controls in place and functioning properly.
 BRG: 96°E (T) LAT: 37.316280 LON: -80.543244 ±13795ft ALT: 2238ft



11081

Figure 3: STA 11096+00 – Controls in place and functioning properly.
 BRG: 103°E (T) LAT: 37.313340 LON: -80.535043 ±98ft ALT: 1910ft



11096

Figure 4: STA 11131+00 – Controls in place and functioning properly.
 BRG: 133°SE (T) LAT: 37.314253 LON: -80.523731 ±164ft ALT: 2050ft



11131