



Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant		
Inspection Date:	Tuesday, June 14, 2022	Project Contact:	Brian Clauto		
Spread G: Montgomery	AR MLV-26 St11668+66-11766+03	Weather:	Dry		

montgomery	St11668+66-11766+03							
ACTIVE STAGE OF CONS	STRUCTION: (Check all that a	ipply)						
☐ Tree Felling	☐ Clearing/Grubbing	☐ Grading		☐ Trenching		☐ Strir		ing/Welding
☐ Lowering/Backfilling	wering/Backfilling \square Final Grading \square Temp. Stabilization \square Perm. Sta		Stabilization	\boxtimes	Dormant			
					,	Yes	No N	N/A
Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?						\boxtimes		
2. Are all co	2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?							
3. Areas of	Areas of offsite sediment deposition observed?						\boxtimes	
 <u>Comments:</u> Inspected the following resources: S-MM21, S-MM22, S-EF65, S-EF62, S-IJ52, W-IJ46 ECD's were in place and functioning at the designated crossings. Routine Maintenance: (<u>72-Hour Deadline from Notification</u>) N/A Ineffective Controls: (<u>24-Hour Deadline from Notification</u>) N/A Recommended Corrective Action: N/A 								
Deadline: N/A								

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:

Date: Tuesday, June 14, 2022

FIELD INSPECTION PHOTO LOG



Project Name: Mountain Valley Pipeline <u>Date</u>: Tuesday, June 14, 2022

 Figure 1: Designated crossing S-MM22, ESC's are in place and functioning.



Figure 2: St11766+03, ECD's and stabilization in place.



 <u>Figure 3</u>: Designated crossing S-MM21, ESC's are in place and functioning.



 <u>Figure 4</u>: Designated crossing S-IJ52, ESC's are in place and functioning.

