

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Monday, April 4, 2022	Project Contact:	Brian Clauto, Cory Chalmers
Spread G: Montgomery County	STA 11788+23 – 11900+00 MVP-MN-266.03	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- Tree Felling
 Clearing/Grubbing
 Grading
 Trenching
 Stringing/Welding
 Lowering/Backfilling
 Final Restoration
 Temp. Stabilization
 Perm. Stabilization
 Dormant

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: N/A.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: _____



Date: Monday, April 4, 2022

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Monday, April 4, 2022

Figure 1: STA 11800+00 – Controls in place and functioning properly.

BRG: 77°E (T) LAT: 37.296114 LON: -80.356226 ±16ft ALT: 2155ft



11800

Figure 2: STA 11825+00 – Controls in place and functioning properly.

BRG: 161°S (T) LAT: 37.286434 LON: -80.355269 ±9842ft ALT: 2212ft



11825

Figure 3: STA 11844+00 – Controls in place and functioning properly.

BRG: 175°S (T) LAT: 37.289593 LON: -80.348660 ±32ft ALT: 2152ft



11844

Figure 4: STA 11885+00 – Controls in place and functioning properly.

BRG: 89°E (T) LAT: 37.287780 LON: -80.339371 ±16ft ALT: 2152ft



11885