

## FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Monday, July 11, 2022	Project Contact:	Brian Clauto, Cory Chalmers
Spread G: Giles County	STA 10819+00 - 10859+34 MVP-GI-241.03/241.02	Weather:	Wet

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)													
	Tree Felling		Clearing/Grubbing		Grading		Trenching		Strii	nging/Welding			
	Lowering/Backfilling		Final Restoration		Temp. Stabilization		Perm. Stabilization	Dormant					
								Yes	No	N/A			
Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?								$\boxtimes$					
Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?							$\boxtimes$						
3. Areas of offsite sediment deposition observed?								$\boxtimes$					
	<u>Comments:</u> In	specte	ed the following resource	es: S-	-A-34, S-A33 and S-Z1	3.							
	<u>Deadline:</u> N/	<u>'A</u>											
	The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.												
	Inspector Sig	natur	e: Marshall	1/1	Willist .								
	Date: Mond	ay, J	uly 11, 2022										



## FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

<u>Date</u>: Monday, July 11, 2022

<u>Figure 1</u>: **STA 10819+00** – Controls in place and functioning properly.



<u>Figure 2:</u> **STA 10836+00** – Controls in place and functioning properly.



<u>Figure 3</u>: **STA 10849+00** – Controls in place and functioning properly.



Figure 4: **STA 10858+00** – Controls in place and functioning properly.

