

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Monday, June 27, 2022	Project Contact:	Brian Clauto, Cory Chalmers
Spread G: Giles County	STA 10593+00 - 10602+18 STA 10660+00 - 10674+92 STA 10705+00 - 10712+73 MVP-GI-238 MVP-LY-029 MVP-GI-240/241.01	Weather:	Rainy

Gile	es County	MVP-GI-238 MVP-LY-029 MVP-GI-240/241.01	weather:	Rainy				
ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)								
	Tree Felling	☐ Clearing/Grubbing ☐ Gr	ading	hing \square	Stringing/Welding			
	Lowering/Backfilling	☐ Final Restoration ☐ Te	mp. Stabilization Perm.	Stabilization 🗵	Dormant			
				Yes	No N/A			
		rols installed and implemented in accord t control plan and stormwater managem		and 🖂				
		ontrol measures properly maintained in ϵ d engineering practices and, where appl						
	3. Areas of	offsite sediment deposition observed?						
	<u>Comments:</u> II	nspected the following resources: S-G2 ²	1 and S-G33.					
	Deadline: N	I <u>/A</u>						
	The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.							
	Inspector Sig	gnature: Mashall Win	Mist .					
	Date: Mone	day, June 27, 2022						

Page **1** of **2**



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Monday, June 27, 2022

<u>Figure 1</u>: **STA 10594+00** – Controls in place and functioning properly.



<u>Figure 2:</u> Laydown Yard 029 – Controls in place and functioning properly.



<u>Figure 3</u>: **STA 10665+00** – Controls in place and functioning properly.



Figure 4: STA 10710+00 – Controls in place and functioning properly.

