

## **FIELD INSPECTION REPORT**

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Tuesday, April 19, 2022	Project Contact:	Brian Clauto, Cory Chalmers
Spread G: Montgomery County	STA 11596+94 - 11620+00 MVP-MN-258.03/258.04/258.05	Weather:	Wet

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)													
			OF C		neck ai					<b>.</b>			
Ш	Tree Felling	lling ☐ Clearing/Grubbing ☐ Grading ☐		Trenching	Ш	Stri	nging/Welding						
	Lowering/B	Backfilling		Final Restoration		Temp. Stabilization		Perm. Stabilization	on 🛭 Dormant				
									Yes	No	N/A		
Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?								erosion and	$\boxtimes$				
	Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?								$\boxtimes$				
	3. Areas of offsite sediment deposition observed?								$\boxtimes$				
<u>Comments:</u> Inspected the following resources: S-OO6, S-RR13 and S-RR14. <u>Recommended Corrective Action</u> : N/A													
	Dead	lline: N//	<u>A</u>										
	The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.												
	Inspe	ector Sigr	nature	e: Mahshar	U IX	Willia?							
	Date	Tuesd	lay, A	April 19, 2022									



## FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

Date: Tuesday, April 19, 2022

Figure 1: **STA 11598+00** – Controls in place and functioning properly.



<u>Figure 2:</u> **Stream S-OO6** – Controls in place and functioning properly along Craig Creek crossing.



<u>Figure 3</u>: **STA 11619+00** – Controls in place and functioning properly.



<u>Figure 4</u>: **Stream S-RR14** – Controls in place and functioning properly along stream crossing.

