

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant		
Inspection Date:	Monday, August 8, 2022	Project Contact:	Brian Clauto		
Spread G: Craig	AR CR 258.01 St11531-114900	Weather:	Dry		

Cra	ig		31-114900			weatner:		Dry				
ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)												
	Tree Felling	☐ Clearing/Grubbing ☐ Grading ☐ Trenching			☐ Stringing/Welding							
	Lowering/Backfilling		Final Grading		Temp	np. Stabilization			ion 🗵	n 🗵 Dormant		
									Yes	No	N/A	
Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?							\boxtimes					
		Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?										
	3. Areas of	offsite	sediment deposition	observe	d?					\boxtimes		
 <u>Comments:</u> Inspected the following resources: S-QQ2, S-PP4, S-PP3, S-PP1 ECD's were in place and functioning at the designated crossings. 												
Routine Maintenance: (<u>72-Hour Deadline</u> from Notification) - N/A												
Ineffective Controls: (<u>24-Hour Deadline</u> from Notification) - N/A												
Recommended Corrective Action: N/A												
											_	
<u>Deadline:</u> N/A												

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: ____

Date: Monday, August 8, 2022

FIELD INSPECTION PHOTO LOG



Project Name: Mountain Valley Pipeline Date: Monday, August 8, 2022

Figure 1: St11531 ECD's and stabilization are in place.



Figure 2: St11498, ECD's and stabilization are in place.



Figure 3: St11493, ECD's and stabilization are in place.




 Figure 4: Designated crossing S-PP1, ECD's and stabilization are in place.

