



Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Monday, November 28, 2022	Project Contact:	Brian Clauto
Spread G: Giles	ATWS 1370, 1370A St 11297-11252 GI 253.02	Weather:	Wet

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)												
☐ Tree Felling		☐ Clearing/Grubbing		bing	☐ Grading		☐ Trenching			String	ging/Welding	
	Lowering/E	Backfilling		Final Grading			Temp. Stabilization		Perm. Stabilization	on 🗵 Dormant		ıant
										Yes	No	N/A
	Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?											
	2.	Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?										
	3.	Areas of o	ffsite s	sediment depos	sition obs	erve	d?				\boxtimes	
 <u>Comments:</u> Inspected the following resources: S-MM18, S-RR2, S-MM17 ECD's were in place and functioning at the designated crossings. 												
Routine Maintenance: (<u>72-Hour Deadline</u> from Notification) - N/A												
Ineffective Controls: (<u>24-Hour Deadline</u> from Notification) - N/A												
Recommended Corrective Action: N/A												
Deadline: N/A												
The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.												
Inspector Signature:												

Monday, November 28, 2022

Date:

FIELD INSPECTION PHOTO LOG



Project Name: Mountain Valley Pipeline

Date: Monday, November 28, 2022

Figure 1: St11297, area is stabilized and ECD's are in place.




Figure 2: Designated crossing S-MM18, ECD's are in place.



■ Figure 3: Designated crossing S-RR2, ECD's are in place.



Figure 4: St11287, area is stabilized and ECD's are in place.

