



Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Monday, September 12, 2022	Project Contact:	Brian Clauto
Spread G: Giles	GI 249.01 ATWS 1464, 1347, 1370, 1370A St11230-11170	Weather:	Dry

Gile			230-11170	1370A						
ACT	IVE STAGE OF C	ONSTRUC	CTION: (Check all the	at apply)						
	Tree Felling	GE OF CONSTRUCTION: (Check all that apply)  Iling   Clearing/Grubbing   Grading   Trenching			Strii	nging/Welding				
	Lowering/Backfil	ling $\square$	Final Grading	Final Grading 🔲 Temp. Stabilization 🔲 Perm. Stabilization		n 🗵 Dormant				
								Yes	No	N/A
Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?						$\boxtimes$				
		2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?								
	3. Area	s of offsite	sediment deposition	observed?					$\boxtimes$	
			llowing resources: N unctioning along th							
Routine Maintenance: ( <u>72-Hour Deadline</u> from Notification) - N/A										
Ineffective Controls: (24-Hour Deadline from Notification) - N/A										
Recommended Corrective Action: N/A										
										_

**Deadline:** N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:


Date: Monday, September 12, 2022

## FIELD INSPECTION PHOTO LOG



**Project Name:** Mountain Valley Pipeline

Date: Monday, September 12, 2022






Figure 3: St11224, ECD's and stabilization are in place.



Figure 4: St11178, ECD's and stabilization are in place.

