

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Monday, May 15, 2023	Project Contact:	Brian Clauto
Spread G: Giles	AR GI 249.01, 249.02, 243.01, 242.01 ATWS 1331, 471	Weather:	Rainy

Ones		ATW	S 1331, 471							
ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)										
☐ Tree F	elling		Clearing/Grubbing		Grading		Trenching		Strir	nging/Welding
☐ Lower	ing/Backfilling		Final Grading		Temp. Stabilization		Perm. Stabilization	\boxtimes	Dorr	mant
								Yes	No	N/A
1.			talled and implement ol plan and stormwate		cordance with the appr gement plans?	roved	erosion and	\boxtimes		
2.	Are all control measures properly maintained in effective operating condition in accordance						\boxtimes			
3.	Areas of	offsite	sediment deposition	observe	d?				\boxtimes	
			llowing resources: S- unctioning at the de							
Routine Maintenance: (<u>72-Hour Deadline</u> from Notification) - N/A										
Ineffective Controls: (<u>24-Hour Deadline</u> from Notification) - N/A										
Recommended Corrective Action: N/A										
Deadline:	N/A									

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: _____

Date: Monday, May 15, 2023



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline Date: Monday, May 15, 2023

 <u>Figure 1</u>: Designated crossing S-NN17, remains undisturbed and ESC measure are in place.



Figure 2: Designated crossing S-Y2, ESC measures in place.



 <u>Figure 3:</u> AR GI 242.01 designated crossing S-MN11, ESC measures in place.



Figure 4: Designated crossing S-Y3, ESC measures in place.

