

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Monday, May 1, 2023	Project Contact:	Brian Clauto, Cory Chalmers
Spread G: Giles County	STA 10759+05 – 10798+83	Weather:	Dry

Giles County	01A 10703+00 10730+00	Weather:	5.9		
ACTIVE STAGE	E OF CONSTRUCTION: (Ch	neck all that apply)			
☐ Tree Felling	☐ Clearing/Grubbing	Grading	☐ Trenching		Stringing/Welding
☐ Lowering/Backfilling	☐ Final Restoration	☐ Temp. Stabilization	Perm. Stabilization	n 🗵	Dormant
				Yes	No N/A
	rols installed and implemented toontrol plan and stormwater		proved erosion and	\boxtimes	
	ontrol measures properly main d engineering practices and, v			\boxtimes	
3. Areas of o	offsite sediment deposition of	bserved?			
<u>Comments:</u> In	nspected the following resour	ces: S-SS4, S-Z9 and S-Z7.			
condition(s) curre	I/A ed corrective action deadline date intly constitute non-compliance are sued to the entity responsible for	nd/or corrective actions are not	completed by the deadline, ot		
Inspector Sig	Maistan	A Willie	1		



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline <u>Date</u>: Monday, May 1, 2023

Figure 1: STA 10764+00 - Controls in place and functioning Figure 2: STA 10776+00 - Controls in place and functioning properly, properly. © 91°E (T) LAT: 37.343970 LON: -80.627439 ±9ft ▲ 2165fr LAT: 37.344788 LON: -80.631457 ±39ft யு ் − Figure 4: STA 10792+00 – Controls in place and functioning Figure 3: STA 10787+00 - Controls in place and functioning properly. properly. **လ** ခ် © 116°SE (T) LAT: 37.342859 LON: -80.623543 ±193ft ▲ 2062ft @ 169°S (T) LAT: 37.343755 LON: -80.624548 ±354ft ▲ 2219f Sold . Ш8-