

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant			
Inspection Date:	Monday, June 26, 2023	Project Contact:	Brian Clau	to		
Spread G: Giles	AR GI 244 Sta 10927-11024 ATWS 1331, 471	Weather:	Dry			
ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)						
Tree Felling	Clearing/Grubbing Clearing	ding 🗌 Trencl	ning		Stringing/We	elding
□ Lowering/Backfilling □ Final Grading □ Temp. Stabilization □ Perm. Stabilization ⊠ Dorma						
				Yes N	lo N/A	
1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?						
2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?						
3. Areas of offsite sediment deposition observed?						
 <u>Comments</u>: Inspected the following resources: S-Y2, S-Y3, S-IJ18, S-IJ19, S-PA 07, S-RR5, S-E25, S-E24. ECD's were in place and functioning at the designated crossing. Routine Maintenance: (<u>72-Hour Deadline</u> from Notification) 						
 Sta 11013+00 CFS requires repair. Sta 10988+00 rill erosion requires repair and re stabilized. 						
Ineffective Controls: (<u>24-Hour Deadline</u> from Notification) - N/A						
Recommended Corrective Action : Maintain and install all controls per the approved PSS&S.						

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:

24

Date: Monday, June 26, 2023



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Monday, June 26, 2023

