

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Monday, August 14, 2023	Project Contact:	Brian Clauto
Spread G: Giles	AR GI256.02 Sta 11330+06-11328 ATWS 1147	Weather:	Wet

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)												
☐ Tree Felling		g		☐ Clearing/Grubbing ☐ Grading ☐ Trenching		Trenching		☐ Stringing/Welding				
	Lowering/B	/Backfilling ☐ Final Grading ☐ Temp		Temp. Stabilization		Perm. Stabilization	\boxtimes	ource Crossing				
									Yes	No	N/A	
Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?							\boxtimes					
	2.	Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?							\boxtimes			
	3.	Areas of o	ffsite	sediment deposition o	bserve	d?				\boxtimes		
 <u>Comments:</u> Inspected the following resources: S-NN13, S-NN14, S-KL43, S-NN12 ECD's were in place and functioning at the designated crossing. 												
Routine Maintenance: (72-Hour Deadline from Notification) - N/A Ineffective Controls: (24-Hour Deadline from Notification) - N/A Recommended Corrective Action: N/A												

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:

Date: Monday, August 14, 2023



FIELD INSPECTION PHOTO LOG



S NN13