

COMPLAINT INVESTIGATION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Monday, September 11, 2023	Project Contact:	Brian Clauto
Spread G: Montgomery County	AR MN 258.04, 258.03 ATWS 1057, 1373 Sta 11618+70-11600	Weather:	Wet

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- Tree Felling
 Clearing/Grubbing
 Grading
 Trenching
 Stringing/Welding
 Lowering/Backfilling
 Final Restoration
 Temp. Stabilization
 Perm. Stabilization
 Other

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Background: This investigation was conducted in response to the PREP complaint 31802. The complaint describe after a rain event on 9/9/23, a severe sediment load remained in Craig Creek, Montgomery Co. VA 5 hours later at 6:30pm from both Sinking Creek mountain ROW as well as Brush Mountain ROW.

Observations:

1. At the time of inspection, a section of ROW between 11618+70 through 11600 was inspected including designated crossings S-RR14, S-RR13, and S-006. Access Roads MN 258.04, 258.03 and ATWS 1057 & 1373 were inspected as well.
2. At the time of the inspection, MVP grading crews were on site prepping the ROW.
3. ECDs within the MVP LOD were installed per the approved plans and appeared to be functioning as designed.
4. MVP reported a rain gauge reading of 1.6 on 9/9/23.

Comments: The following resources were inspected during the onsite complaint investigation: S-RR14, S-RR13, S-006

Routine Maintenance: (72-Hour Deadline from Notification)

- N/A


Corrective action: (24-Hour Deadline from Notification)

- N/A

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: 

Date: Monday, September 11, 2023

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Monday, September 11, 2023

Figure 1: Designated stream S-RR13, ECD's were in place for active construction.



Figure 2: Upstream of designated stream S-RR13.



Figure 3: Downstream of S-RR13.



Figure 4: Designated crossing S-RR14, ECD's were in place for active construction.



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Monday, September 11, 2023

Figure 5: Upstream of S-RR14 crossing.



Figure 6: Downstream of S-RR14 crossing.



Figure 7: Sta 11615+30, ECD appears to be functioning above S-RR14.



Figure 8: Designated crossing S-006, ECD's were in place.



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Monday, September 11, 2023

Figure 9: Upstream of S-006 crossing.



Figure 10: Downstream of S-006 crossing.



Figure 7: Sta 11602, ECD were in place.



Figure 8: AR MN 258.03, ECD's were in place.

