

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant		
Inspection Date:	Wednesday, September 20, 2023	Project Contact:	Brian Clauto		
Spread G: Giles	Sta 10530-105519+31, 10592+79- 10600, 11641+57-10656 ATWS 610, 610A, 1124, 1130, 815, 339A, 1135, 1136 AR GI234, 235, 236, 238, 239	Weather:	Dry		

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)												
	☐ Tree Felling		\boxtimes	Clearing/Grubbing		Grading		Trenching		Stringing/Welding		
\boxtimes	Lowering/E	ing/Backfilling		Final Grading		Temp. Stabilization		Perm. Stabilization	n 🗵 Reso		ource Crossing	
									Yes	No	N/A	
	1.			alled and implemente I plan and stormwate		cordance with the approper	oved	erosion and	\boxtimes			
	2.	Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?							\boxtimes			
	3.	Areas of of	fsite	sediment deposition of	bserve	d?	·			\boxtimes		
-	Comments:	Inspected t	he fol	lowing resources: S-0	Q14, S-	Q13, S-S5					1	
Routine Maintenance: (<u>72-Hour Deadline</u> from Notification) - N/A												
Ineffective Controls: (24-Hour Deadline from Notification) - N/A												
Recommended Corrective Action: N/A												

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: _____

Date: Wednesday, September 20, 2023



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, September 20, 2023

Figure 1: Designated crossing S-Q13, ECD's are in place.





Figure 3: Designated crossing S-S5, ECD's are in place.



Figure 4: Sta11641+57, ECD's are in place.

